

PHOTO MOUNTING SHEET

Insured: Asheville Crane, Inc.	Claim Number: ILM216252
Date Taken: 11/11/2011	Our File Number: 1111-01617-KS



Photo #1: View of 2003 Linkbelt ATC-822, 22-ton, All-Terrain Crane SN: 71J35776, with 70' main and 45' jib.



Photos #2: Unit hit soft spot and rolled down the side of a mountain about 20'-25' from driveway.



Photo #3: View depicting damage to boom cab and aluminum decking.



Photo #4: Front view of boom cab.



Photo #5: Front view – depicting damage to carrier cab.



Photo #6: Interior view of carrier cab.



Photo #7: View depicting damage to jib and fly.



Photo #8: Equipment lodged against tree. Impact damaged jib.



Photo #9: View depicting fly.



Photo #10: Front view of unit on side of mountain.



Photo #11: Right side view of boom truck lodged against tree on side of mountain.



Photo #12: View of crane recovered from loss site.



Photo #13: Right side view of boom truck recovered from site. Boom has been removed.



Photo #14: View depicting boom section.



Photo #15: View depicting boom and jib. Damage to jib from impact. No visible damage to boom.



Photo #16: View of boom sections.



Photo #17: Additional view of platform decking.



Photo #18: View of Cummins 6-cylinder, ISB series engine. No visible damage to engine.

(Radiator/cooling system is damaged).



Photo #19: Radiator/Cooling system sustained damaged from impact.



Photo #20: View of loss location. Insured was operating unit down driveway, hit soft spot and rolled over down mountain approx. 20'.



Photo #21: Insured's work included the truss erection for homeowner's new building on mountain site.



Photo #22: Insured will need to build up driveway in order to bring in (2) 70-ton cranes for recovery.