

## Property Damage Appraisers (PDA Toledo)

Damage Assessed By:

Classification: None

Condition Code: Good  
 Date of Loss: 4/ 8/2015  
 Contact Date: 4/ 9/2015  
 Deductible: UNKNOWN  
 File Number:  
 Claim Number:

Type of Loss: Property Damage  
 Arrival Date: 4/10/2015  
 Accident Date: 4/ 8/2015

Insured:  
 Owner:  
 Address:  
 Telephone:

Description: 2005 Mack Vision CX  
 Type/Component: Truck  
 VIN: 1M1AK07Y95N007016  
 Mileage: 547,796  
 OEM/ALT: O  
 Color: White

Vehicle Production Date: 1/05  
 Drive Train:  
 License: PGM8296 OH

| Line Item | Entry Number | Labor Type | Operation      | Line Item Description                | Part Type/<br>Part Number | Dollar Amount | Labor Units |
|-----------|--------------|------------|----------------|--------------------------------------|---------------------------|---------------|-------------|
| 1         | 100002       | REF        | REFINISH       | Frnt Face Bar Complete               |                           |               | 3.0         |
| 2         | 100006       | BDY        | REMOVE/REPLACE | R Frnt Bumper Face Bar               | N.A.                      | 1,282.72 *    | 1.1 #       |
| 3         | 100007       | BDY        | REMOVE/REPLACE | L Frnt Bumper Face Bar               | N.A.                      | INC*          | 1.1 #       |
| 4         | 100008       | BDY        | REMOVE/REPLACE | Frnt Bumper Support                  | N.A.                      | INC*          | 0.7 #       |
| 5         | 100009       | BDY        | REMOVE/REPLACE | R Frnt Inr Bumper Bracket            | N.A.                      | 48.72 *       | 0.3 #       |
| 6         | 100010       | BDY        | REMOVE/REPLACE | L Frnt Inr Bumper Bracket            | N.A.                      | 48.72 *       | 0.3 #       |
| 7         | 100011       | BDY        | REMOVE/REPLACE | R Frnt Otr Bumper Bracket            | N.A.                      | 55.58 *       | 0.3 #       |
| 8         | 100012       | BDY        | REMOVE/REPLACE | L Frnt Otr Bumper Bracket            | N.A.                      | 55.58 *       | 0.3 #       |
| 9         | 100013       | BDY        | REMOVE/REPLACE | R Frnt Bumper Tube                   | N.A.                      | 77.61 *       | 0.3 #       |
| 10        | 100014       | BDY        | REMOVE/REPLACE | L Frnt Bumper Tube                   | N.A.                      | 77.61 *       | 0.3 #       |
| 11        | 100017       | BDY        | REMOVE/REPLACE | Grille                               | N.A.                      | 531.72 *      | 1.1         |
| 12        | 101078       | BDY        | REMOVE/REPLACE | Grille Screen                        | N.A.                      | 138.59 *      | 1.0         |
| 13        | 100022       | BDY        | CHECK/ADJUST   | Headlamps                            |                           |               | 0.5         |
| 14        | 100026       | BDY        | REMOVE/REPLACE | L Frnt Combination Lamp Assembly     | Qual Recycled Part        | 303.90 *      | 1.5 r       |
| 15        |              |            |                | LKQ Goody's Truck Parts 800-537-8690 |                           |               |             |
| 16        | 100053       | REF        | REFINISH       | Hood Outside                         |                           |               | 8.7         |
| 17        | 100054       | REF        | REFINISH       | Hood Underside                       |                           |               | 3.5         |
| 18        | 100061       | BDY        | REMOVE/REPLACE | Hood Panel                           | N.A.                      | 3,722.88 *    | 8.0 #       |
| 19        | 100082       | BDY        | REMOVE/INSTALL | Radiator                             |                           |               | 3.5         |
| 20        | 100164       | FRM        | REPAIR         | R Frame Rail -F                      | Existing                  |               | 9.0* #      |
| 21        | 100165       | FRM        | REPAIR         | L Frame Rail -F                      | Existing                  |               | 9.0* #      |
| 22        | 900500       | MCH*       | REMOVE/REPLACE | Alignment                            | New                       | 200.00 *      | 0.0*        |
| 23        | 100196       | BDY        | REMOVE/REPLACE | L Fuel System Tank                   | N.A.                      | 1,727.44 *    | 2.0 #       |
| 24        | 100228       | BDY        | REMOVE/REPLACE | L Uprr Fuel System Step              | N.A.                      | 160.47 *      | 0.5         |
| 25        | 101138       | BDY        | REMOVE/REPLACE | L Lwr Fuel System Step               | N.A.                      | 160.47 *      | 0.5         |
| 26        | 100230       | BDY        | REMOVE/REPLACE | L Support 2@94.10                    | N.A.                      | 188.20 *      | 0.6         |
| 27        | 100232       | BDY        | REMOVE/REPLACE | L Step Bracket 2@207.42              | N.A.                      | 414.83 *      | 0.6 #       |
| 28        | 100234       | BDY *      | REMOVE/REPLACE | L Step Bracket 2@207.42              | N.A.                      | 414.83 *      | 0.6 #       |
| 29        | 101129       | MCH*       | REMOVE/REPLACE | Alloy Wheel 2@352.38                 | Qual Recycled Part        | 704.76 *      | 2.8* #      |
| 30        |              |            |                | LKQ Goody's Truck Parts 800-537-8690 |                           |               |             |

ESTIMATE RECALL NUMBER: 04/13/2015 16:52:21 2625040055  
 Mitchell Data Version: OEM: APR\_15\_V

|    |        |       |                |                                     |    |          |          |   |        |
|----|--------|-------|----------------|-------------------------------------|----|----------|----------|---|--------|
| 31 | 100251 | MCH   | REMOVE/REPLACE | Frnt Susp Axle                      | -M | N.A.     | 4,387.00 | * | 9.0    |
| 32 | 100263 | MCH   | REMOVE/REPLACE | R Frnt Susp Leaf Spring             | -M | N.A.     | 704.76   | * | 1.7 #  |
| 33 | 100264 | MCH   | REMOVE/REPLACE | L Frnt Susp Leaf Spring             | -M | N.A.     | 704.76   | * | 1.7 #  |
| 34 | 100265 | MCH   | REMOVE/REPLACE | R Frnt Susp Front Spring Hanger     | -M | N.A.     | 229.42   | * | 0.5 #  |
| 35 | 100266 | MCH   | REMOVE/REPLACE | L Frnt Susp Front Spring Hanger     | -M | N.A.     | 240.50   | * | 0.5 #  |
| 36 | 100394 | REF   | REFINISH       | Cab Front Panel Outside             |    |          |          |   | C 3.8  |
| 37 | 100406 | BDY   | REPAIR         | Cab Front Panel                     |    | Existing |          |   | 6.0* # |
| 38 | 100410 | BDY   | REMOVE/REPLACE | R Splash Shield                     |    | N.A.     | 61.39    | * | 1.1    |
| 39 | 100411 | BDY   | REMOVE/REPLACE | L Splash Shield                     |    | N.A.     | 58.97    | * | 1.1    |
| 40 | 100979 | BDY   | REMOVE/REPLACE | L Qtr Fender Mud Flap               |    | N.A.     | 13.70    | * | 0.1    |
| 41 | 100981 | BDY   | REMOVE/REPLACE | L Qtr Fender                        |    | N.A.     | 322.24   | * | 0.3 #  |
| 42 | 100983 | BDY   | REMOVE/REPLACE | L Qtr Fender Mounting Bracket       |    | N.A.     | 38.00    | * | 0.2 #  |
| 43 | 100998 | BDY   | REMOVE/REPLACE | L Rear Mud Flap                     |    | N.A.     | 13.70    | * | 0.3 #  |
| 44 | 101000 | BDY   | REMOVE/REPLACE | L Rear Mud Flap Bracket             |    | N.A.     | 38.00    | * | 0.3 #  |
| 45 | 101004 | BDY   | REMOVE/REPLACE | L Rear Combination Lamp Assembly    |    | N.A.     | 298.39   | * | 0.4 #  |
| 46 | 101008 | BDY   | REMOVE/REPLACE | Rear Combination Lamp Mount         |    | N.A.     | 0.00     | * | 0.5 #  |
| 47 | AUTO   | REF   | ADD'L OPR      | Clear Coat                          |    |          |          |   | 0.8    |
| 48 | 900500 | BDY * | REMOVE/REPLACE | Shop Supplies                       |    | New      | 250.00   | * | 0.0*   |
| 49 | 900500 | MCH * | REMOVE/REPLACE | Lt Frt Steer Tire                   |    | New      | 597.00   | * | 0.8*   |
| 50 |        |       | BETTERMENT - P | Lt Frt Steer Tire %20.00            |    |          | 119.40   |   |        |
| 51 | 900500 | MCH * | REMOVE/REPLACE | Lt Rear Frt Outer Recap Tire        |    | New      | 387.00   | * | 0.8*   |
| 52 |        |       | BETTERMENT - P | Lt Rear Frt Outer Recap Tire %20.00 |    |          | 77.40    |   |        |
| 53 | 900500 | MCH * | REMOVE/REPLACE | Lt Frt Lug Studs 8@11.19            |    | New      | 89.50    | * | 1.0*   |
| 54 | AUTO   |       | ADD'L COST     | Paint/Materials                     |    |          | 990.00   | * |        |

\* - Judgment Item  
 # - Labor Note Applies  
 C - Included in Clear Coat Calc  
 r - CEG R&R Time Used For This Labor Operation

### Estimate Totals

| I. Labor Subtotals  | Units | Rate  | Add'l Labor Amount | Sublet Amount | Totals                       | II. Part Replacement Summary   | Amount    |
|---|-------|-------|--------------------|---------------|------------------------------|--------------------------------|-----------|
| Body  | 35.4  | 85.00 | 0.00               | 0.00          | 3,009.00 T                   | Taxable Parts                  | 18,748.96 |
| Refinish  | 19.8  | 85.00 | 0.00               | 0.00          | 1,683.00 T                   |                                |           |
| Frame   | 18.0  | 85.00 | 0.00               | 0.00          | 1,530.00 T                   | Total Replacement Parts Amount | 18,748.96 |
| Mechanical  | 18.8  | 95.00 | 0.00               | 0.00          | 1,786.00 T                   |                                |           |
| Taxable Labor   |       |       |                    |               | 8,008.00                     |                                |           |
| Labor Summary   | 92.0  |       |                    |               | 8,008.00                     |                                |           |
| III. Additional Costs                                       |       |       |                    |               | Amount                       | IV. Adjustments                |           |
| Taxable Costs   |       |       |                    |               | 990.00                       | Betterment                     |           |
| Total Additional Costs                                      |       |       |                    |               | 990.00                       | Customer Responsibility        |           |
| Paint Material Method: Rates                                |       |       |                    |               |                              |                                |           |
| Init Rate = 50.00 , Init Max Hours = 99.9, Addl Rate = 0.00 |       |       |                    |               |                              |                                |           |
|   |       |       |                    |               | I. Total Labor:              |                                | 8,008.00  |
|   |       |       |                    |               | II. Total Replacement Parts: |                                | 18,748.96 |
|   |       |       |                    |               | III. Total Additional Costs: |                                | 990.00    |
|   |       |       |                    |               | Gross Total:                 |                                | 27,746.96 |

Date: 4/13/2015 04:52 PM  
Estimate ID:  
Estimate Version:  
Committed  
Profile ID:

|     |                    |                   |
|-----|--------------------|-------------------|
| IV. | Total Adjustments: | 196.80-           |
|     | Net Total:         | 27,550.16         |
|     |                    | <b>TOTAL LOSS</b> |

Point(s) of Impact

12 Front Center (P)

Insurance Co:  
Address:

Work Phone:

Inspection Site:  
Address:

Inspection Date: 4/10/2015



Document Name: VIN.JPG

Remarks:



Document Name: ODOMETER.JPG

Remarks:



Document Name: INTERIOR.JPG

Remarks:



Document Name: LICENSE.JPG

Remarks:



Document Name: LEFTFRONT.JPG

Remarks:



Document Name: RIGHTFRONT.JPG

Remarks:



Document Name: LEFTREAR.JPG

Remarks:



Document Name: RIGHTREAR.JPG

Remarks:



Document Name: P1050471.JPG

Remarks: Rt cowel damage



Document Name: P1050472.JPG

Remarks: Rt frame rail damage





Document Name: P1050455.JPG

Remarks: Frt view



Document Name: P1050457.JPG

Remarks: Frt axle damage



Document Name: P1050458.JPG

Remarks: Lt frame rail damage,good chance that gear box and coolers have damage ,cannot raise hood



Document Name: P1050459.JPG

Remarks: Lt frt wheel and tire damage



Document Name: P1050460.JPG  
Remarks: Lt fuel tank and step damage



Document Name: P1050462.JPG  
Remarks: Lt side cowel damage



Document Name: P1050466.JPG  
Remarks: Lt frt mudflap and tire damage



Document Name: P1050467.JPG  
Remarks: Lt re mudflap damage



Document Name: P1050468.JPG

Remarks: Rear lamp and crossmember damage