

August 12, 2010

RE: Damaged Carrier Units

Mechanical Contractors Inc specifically inch

Replace

- 1 - 8.5 Ton Carrier Condenser Coil Model # 48TCD
 - 2 - 10 Ton Carrier Condenser Coils Model # 48TCE
 - 1 - 12.5 Ton Carrier Condenser Coil Model# 48TCE
- Please see Price Break down Below:
- 1 - 8.5 Ton Condenser Coil
 - 2 - 10 Ton Condenser Coils
 - 1 - 12.5 Condenser Coil

Labor

- 8 Man hours per Unit x4 Units @ \$150 per Man hour
- 20 LBS 410A Refrigerant @ \$45 per LB.....
- Solder.....
- Oxygen & Acetylene.....
- 2 Tanks Nitrogen @ \$30 each.....

**Please note any other Damage found during removal

President

Mechanical Contractors, Inc.

1000 N. ...

Industrial

includes the following scope of work listed below;

- D09A2A6-0A0A0
- D12A2G6-0A0A0
- D14A3G6-0A0A0

Coil Cost: \$ 12,992.00

.....	\$ 4,800.00
.....	\$ 900.00
.....	\$ 50.00
.....	\$ 65.00
.....	\$ 60.00
Total Repair Cost:	\$ 18,867.00

Value of Coils is not included in above price.