

Initial Summary Report

IANet File Number: 495928		Today's Date: 2/9/2012 7:15:00 AM	
Claim Number: c017089-3		Date of first contact: 2/3/2012	
Policy Number: PIA03064605		Date of inspection: 2/6/2012	
Insured/Claimant: / William Begella		Shop name: Copart	
Appraisal Type: 2		Shop phone:	
Appraiser's Name:		Shop IRS #:	
Appraisal Company: IAnet-Don Creek		Damages consistent with facts of loss: Yes	
Inspection Location: 2889 E US Highway 60 Rogersville mo 65742			
REPAIRABLE		TOTAL LOSS	
		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> BORDERLINE	
Gross Appraisal:	\$10,933.98	TLV Form:	
Deductible: -		Request Number:	
Other Deductions: -	\$0.00	Net ACV/Instant Value:	0
-	\$0.00	Tax: +	0
Other Additions: +	\$0.00	Ded: -	\$0.00
+	\$0.00	Total:	\$0.00
Total:		Salvage Moved:	No
Drivable:	No	Salvage Location:	
Agreed Price:	No	Stock Number:	
Days to Repair:	30	Collecting Storage:	
Estimate given to:	No Copy Given Out	Amount per day:	
Shop Estimate Amount:		Salvage bids obtained: <input type="checkbox"/> YES <input type="checkbox"/> NO	
Tow Charges:		Salvage Bids	
Primary Damage:	Rollover	Company Contact Phone Number Amount	
Secondary Damage:	0	1)	
Unrelated Damage:		2)	
Open Damages:		3)	
LKQ Searches		A/M Searches	
Name of source Phone number/Website		Name of source Phone number/Website	
1)		1)	
2)		2)	
3)		3)	

Drove to Coparts in Rogersville Mo for this inspection. Had rolled on the right side and heavy damages. Understand it's worth 30-40K. Could not tell how long to repair because of the age and the ability to find the parts.

Auditor Notes:

IA NET ACCURATE NATIONWIDE APPRAISALS
PHONE: 480-596-1105 FAX: 480-596-1140
SUPPLEMENTS@IANETWORK.NET

*** PRELIMINARY ESTIMATE ***

RO# 495928

02/07/2012 12:31 PM

Owner

Owner: William Begella
Address: 7381 California
City State Zip: Youngstown, OH 44501

Work/Day:
FAX:

Control Information

Claim # : C017089-3
Loss Date/Time: 01/29/2012
Deductible: Unknown
File # : IANET # 495928

Insured Policy # : PIA03064605
Loss Type: Liability

Accounting # :

Ins. Company: Canal Ins Company

Insured: Unknown

Claimant: William Begella
Address: 7381 California
City State Zip: Youngstown, OH 44501

Work/Day:
FAX:

Claim Rep: Christina Heald

Inspection

Inspection Date: 02/06/2012
Inspection Location: Coparts
Address: 2889 E US Highway 60
City State Zip: Rogersville, MO 65742
Primary Impact: Right Side

Inspection Type: Field
Contact:
Work/Day:
FAX:
Secondary Impact:

Appraiser Name: Don Creek
Address: 7819 E. Greenway Road
Suite 6
City State Zip: Scottsdale, AZ 85260

Appraiser License # :
Work/Day: (480)596-1105
Home/Evening:
FAX: (480)596-1140

Repairer

Repairer: Unknown

Contact:

Target Complete Date/Time:

Days To Repair: 20

Remarks

* For All Supplement Utilize IAnet Accurate Nationwide Appraisals 480-596-1105
supplements@ianetwork.net
* All completed appraisals are subject to Insurance Company Review and
approval prior to the Company accepting the appraisal as a repair agreement
* Requirements for all supplement requests: Receipts, Old Parts, Photos, etc.
* This estimate is for visible damages only. Authorization for teardown should
be obtained from the vehicle owner and a complete tear down done prior to

ordering parts or proceeding with the repairs *

Vehicle

1956 Chevrolet Panel STD 2 DR Wagon

Lic.Plate: NONE
Lic Expire:
Prod Date:
Veh Insp# :
Condition:
Ext. Color: Red/Cream
Ext. Refinish: Two-Stage

Lic State:
VIN: 3A5660013832
Mileage: 96,609
Mileage Type: Actual
Code: T999Z2
Int. Color:
Int. Refinish:

Options

Damages

Line	Op	Guide	MC	Description	MFR.Part No.	Price	ADJ%	B%	Hours	R
1	EC	14		Extn,Front Bumper Otr RT	Replace Economy	\$99.99*	+25.00		1.5*	SM
2	I	83		Panel,Hood	Repair				4.0*	SM
3	L	83		Panel,Hood	Refinish				4.5*	RF
4	EU	104		Fender,Front RT	LIKE KIND & QUAL.PRT	\$275.00*			4.0*	SM
5	L	104		Fender,Front RT	Refinish				4.5*	RF
6	EU	143		Windshield	LIKE KIND & QUAL.PRT	\$175.00*	+25.00		1.0*	SM
7	I	188		Panel,Rocker RT	Repair				5.0*	SM
8	L	188		Panel,Rocker RT	Refinish				3.0*	RF
9	EU	231		Door Assembly,Front RT	LIKE KIND & QUAL.PRT	\$675.00*	+25.00		4.0*	SM
10	L	231		Door Shell,Front RT	Refinish				5.0*	RF
11	EU	255		Glass,Front Door T RT	LIKE KIND & QUAL.PRT	\$75.00*	+25.00			SM
12	I	322		Panel,Roof	Repair				24.0*	SM
13	L	322		Panel,Roof	Refinish				8.0*	RF
14	I	357		Panel,Quarter RT	Repair				35.0*	SM
15	L	357		Panel,Quarter RT	Refinish				6.0*	RF
16	L			Corrosion Protection	Refinish	\$12.50*				SM
17	L			Cover Car Exterior	Refinish	\$7.00*				SM
18	SB			Hazardous Waste Removal	Sublet Repair	\$3.50*				SM
19	EU			Windshield Header	LIKE KIND & QUAL.PRT	\$129.95*	+25.00		1.0*	SM*
20	L			Refinish Header	Refinish				2.5*	RF*
21	EU			3100 Emb	LIKE KIND & QUAL.PRT	\$75.00*	+25.00		0.3*	SM*
22	EU			Right Headlamp Bezel	LIKE KIND & QUAL.PRT	\$25.00*	+25.00		0.2*	SM*
23	EU			Right Mirror	LIKE KIND & QUAL.PRT	\$75.00*	+25.00		0.3*	SM*
24	EC			Right Radio Ant	Replace Economy	\$25.00*	+25.00		0.2*	SM*
25	I			Right Rear Drip Rail	Repair				5.0*	SM*
26	L			Refinishf Drip Rail	Refinish				1.5*	RF*
27	N			R&I Interior As Needed	Additional Labor				3.0*	SM*
28	L			Two Tone Paint	Refinish				4.0*	RF*
29	R			R&I Right Taillamp	R & I Assembly				0.3*	SM*
29 Items										

Estimate Total & Entries

Other Parts	\$1,649.44	
Paint Materials	\$450.00**	
Line Item Markup	\$338.74	
Parts & Material Total		\$2,438.18
Tax on Parts & Material	@ 7.600%	\$185.30

Labor	Rate	Replace Hrs	Repair Hrs	Total Hrs	
Sheet Metal (SM)	\$65.00	12.8	76.0	88.8	\$5,772.00
Mech/Elec (ME)	\$65.00				
Frame (FR)	\$65.00				
Refinish (RF)	\$65.00	39.0		39.0	\$2,535.00
Paint Materials	\$34.00				
Labor Total				127.8 Hours	\$8,307.00
Sublet Repairs					\$3.50
Gross Total					\$10,933.98
Less: Deductible					Unknown-
Net Total					\$10,933.98


Alternate Parts C/00/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 65809 Springfield MO
 Recycled Parts No

Audatex Estimating 6.0.726 ES 02/07/2012 12:55 PM REL 6.0.726 DT 12/01/2011
 Copyright (C) 2011 Audatex North America, Inc.

**** USER-ESTABLISHED THRESHOLD FOR PAINT MATERIALS HAS BEEN REACHED AND CALCULATED IN THIS ESTIMATE. ANY ADDITIONAL MATERIALS MAY REQUIRE FURTHER APPROVAL. ****

Op Codes

* = User-Entered Value	E = Replace OEM	NG = Replace NAGS
EC = Replace Economy	OE = Replace PXN OE Srpls	UE = Replace OE Surplus
ET = Partial Replace Labor	EP = Replace PXN	EU = LIKE KIND & QUAL.PRT
TE = Partial Replace Price	PM = Replace PXN Reman/Rebtl	UM = Replace Reman/Rebuilt
L = Refinish	PC = Replace PXN Reconditioned	UC = Replace Reconditioned
TI = Two-Tone	SB = Sublet Repair	N = Additional Labor
BR = Blend Refinish	I = Repair	IT = Partial Repair
CG = Chipguard	RI = R & I Assembly	P = Check
AA = Appearance Allowance	RP = Related Prior Damage	



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

Copyright (C) 2011 Audatex North America, Inc.
 Audatex Estimating is a trademark of Audatex North America, Inc.